

# Error memory

Date: 2/24/23, 2:35 PM  
VIN: WBA8B3G56GNT91939

## 10 Central gateway module

### 3 errors

CD0420: Error in the Flexray controller on the Flexray bus

CD0487: Synchronization process failed, CC was not yet synchronized when the error memory lock was released

801C20: Central fault memory full

## 12 Motor electronics

### 1 error

213901: Power management: active consumer reduction

## 1C Integrated chassis management

### 2 errors

480134: SBS function - direction of travel unsafe with vx greater than 2 m / s

D014A1: Signal error (actual position EPS, ID: AVL\_PO\_EPS) qualifier

## 40 Car access system

### 8 errors

804080: Ignition on: startability endangered

8040B7: Deactivation of terminal 15: OSFG reached

8040B9: Deactivation of terminal 30B: OSFG reached

8040BB: KI30B active: start capability limit reached or KI. 30B active for a long time

8040BD: Terminal 30F reset or shutdown

8041A8: Welcome Light repeat lock active

8041AB: Deep discharge protection of the battery: deactivation of parking light

8041B2: Light active: start capability limit reached