

Error memory

Date: 3/19/22, 7:51 PM

VIN: WBA3R1C57GK529134

12 Motor electronics

2 errors

110001: Cylinder injection shutdown: catalyst protection due to too low pressure in the fuel system

11A002: High fuel pressure, plausibility: pressure too low

3F Active sound design

1 error

8053A5: Invalid encoding data for Equalizing