

AZD-AZD-AZDMUC3332-F2X_F3X Trailing arms and struts

VIN: F774315

Vehicle: 4' / F32 / Coupe / 435i / N55 / USA / left-hand drive / MANUAL / 2014 / 1

System version: 1.1.5

Data version: 3.42

33 32 Trailing arms and struts

	Type	Thread	Tightening specifications	Dimension
1AZ Trailing arm to rear axle support	F20 / F21 / F22 / F30 / F31 / F32 / F33 / F34 / F35	M12	Replace nut. Tighten down in normal position.	100 Nm
2AZ Trailing arm to wheel carrier	F20 / F21 / F22 / F30 / F31 / F32 / F33 / F34 / F35	M12	Replace nut. Tighten down in normal position.	100 Nm
3AZ Control arm to rear axle support	F20 / F21 / F22 / F30 / F31 / F32 / F33 / F34 / F35	M12	Replace nut. Tighten down in normal position.	100 Nm
4AZ Guide arm to wheel carrier	F20 / F21 / F22 / F30 / F31 / F32 / F33 / F34 / F35	M12	Replace screw. Tighten down in normal position. Jointing torque Angle of rotation	100 Nm 90 °
5AZ Wishbone to rear axle support	F20 / F21 / F22 / F30 / F31 / F32 / F33 / F34 / F35	M12	Replace nut. Tighten down in normal position.	100 Nm
6AZ Wishbone to wheel carrier	F20 / F21 / F22 / F30 / F31 / F32 / F33 / F34 / F35	M12	Replace screw. Tighten down in normal position. Jointing torque Angle of rotation	100 Nm 90 °
7AZ Toe arm to rear axle support	F20 / F21 / F22 / F30 / F31 / F32 / F33 / F34 / F35	M12	Replace nut. Tighten down in normal position.	100 Nm
8AZ Toe arm to wheel carrier	F20 / F21 / F22 / F30 / F31 / F32 / F33 / F34 / F35	M12	Replace screw. Tighten down in normal position. Jointing torque Angle of rotation	100 Nm 90 °
9AZ Camber arm to rear axle support	F20 / F21 / F22 / F30 / F31 / F32 / F33 / F34 / F35	M14	Replace nut. Tighten down in normal position.	165 Nm
10AZ Camber arm to wheel carrier	F20 / F21 / F22 / F30 / F31 / F32 / F33 / F34 / F35	M14	Replace nut.	165 Nm
11AZ Aerodynamic cover on camber arm	F20 / F21 / F22 / F30 / F31 / F32 / F33 / F34 / F35	M6	Replace nuts.	4 Nm
12AZ Tension strut to body	F20 / F21 / F31 / F32 / F33 / F34	M8		24 Nm
13AZ Tension strut to compression strut	F20 / F21 / F31 / F32 / F33 / F34		Replace screws. Jointing torque Angle of rotation	100 Nm 90 °