

Error memory

Date: 12/3/21, 19:12

VIN: WBA3R1C57GK529134

06 Allround-view camera

1 error

800BAA: CVBS output: interruption or not connected

10 Central gateway module

4 errors

CD0487: Synchronization process failed, CC was not yet synchronized when the error memory lock was released

801C10: Request to reset terminal 30F alarm clock

801C12: Send powerdown

801C13: Request to reset terminal 30F asleep

12 Motor electronics

2 errors

11A002: High fuel pressure, plausibility: pressure too low

128B01: Lambda probe before catalytic converter: air leakage detected

17 Electronic fuel pump control module

1 error

481B03: Motor current too low

60 Instrument panel

1 error

E12C1D: Information: Terminal 30f was switched off (terminal 30 delay time controlled by errors, 0x3AC)

61 Combox emergency call

1 error

03178A: SIF: General Mobile Network Errors

63 Headunit/radio

2 errors

E1C440: reset

E1C603: Ethernet: communication error (link abort) due to control unit reset

78 Automatic heating and air conditioning

1 error

801225: Compressor: shutdown due to negative pressure in the refrigerant circuit